## FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL HARDWARE NUMBER:05-6PP-3005SW -X

SUBSYSTEM NAME: GPS THREE STRING

REVISION: 0

04/09/97

PART DATA

PART NAME **VENDOR NAME** 

PART NUMBER **VENDOR NUMBER** 

LRU

:PANEL 07

VO70-730390

SRU

:SWITCH, TOGGLE

ME452-0102-7601

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

SWITCH TOGGLE, 1-POLE, 2-POSITION

- ."

REFERENCE DESIGNATORS:

33V73A7S37

33V73A7S39

33V73A7S41 33V73A7S43 33V73A7S45

33V73A7S47

QUANTITY OF LIKE ITEMS:

SIX

FUNCTION:

SWITCHES POWER TO THE UPPER OR LOWER GPS PREAMPLIFIER.

FAILURE MODES EFFECTS ANALYSIS FMEA -- NON-CIL FAILURE MODE

NUMBER: 05-6PP-3005SW-01

REVISION#: A

10/14/99

SUBSYSTEM NAME: GPS THREE STRING

LRU: PANEL 07

ITEM NAME: SWITCH, TOGGLE

CRITICALITY OF THIS FAILURE MODE: 1R3

FAILURE MODE:

FAILS OPEN, SHORT-TO-CASE

MISSION PHASE:

DO DE-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY:

102 COLUMBIA

103 DISCOVERY

104 ATLANTIS

105 **ENDEAVOUR** 

CAUSE:

PIECE PART STRUCTURAL FAILURE, CONTAMINATION, VIBRATION, MECHANICAL SHOCK, PROCESSING ANOMALY

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN

A) PASS

B) PASS

C) PASS

PASS/FAIL RATIONALE:

A)

B)

C)

- FAILURE EFFECTS -

## (A) SUBSYSTEM:

LOSS OF POWER TO ONE PREAMPLIFIER.

## (B) INTERFACING SUBSYSTEM(S):

LOSS OF PREAMPLIFIER RESULTS IN LOSS OF GPS SIGNALS FROM ONE OF TWO ANTENNAS FOR ONE OF THREE GPS RECEIVER STRINGS. CAUSES PARTIAL LOSS OF PAGE: 3

PRINT DATE: 10/19/99

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL FAILURE MODE NUMBER: 05-6PP-3005SW-01

SATELLITE RECEPTION COVERAGE FOR ONE GPS RECEIVER BUT ALLOWS THAT GPS RECEIVER TO CONTINUE FUNCTIONING.

(C) MISSION:

NO EFFECT

(D) CREW, VEHICLE, AND ELEMENT(S):

NO EFFECT - FIRST FAILURE. OPERATIONS CONTINUE WITH PARTIAL RECEPTION LOSS OF ONE GPS RECEIVER STRING. NO EFFECT - SECOND FAILURE ON THE SAME STRING. LOSS OF ONE GPS RECEIVER STRING. OPERATIONS CONTINUE WITH TWO REMAINING STRINGS. POSSIBLE LOSS OF CREW/VEHICLE AFTER THIRD AND FOURTH FAILURE WHERE THE TWO REMAINING GPS RECEIVERS FAIL (LOSS OF OUTPUT, ERRONEOUS OUTPUT) DUE TO INABILITY TO MAKE LANDING SITE.

## (E) FUNCTIONAL CRITICALITY EFFECTS:

NO EFFECT

- TIME FRAME -

TIME FROM FAILURE TO CRITICAL EFFECT: N/A

TIME FROM FAILURE OCCURRENCE TO DETECTION: SECONDS

TIME FROM DETECTION TO COMPLETED CORRECTING ACTION: N/A

IS TIME REQUIRED TO IMPLEMENT CORRECTING ACTION LESS THAN TIME TO EFFECT? N/A

RATIONALE FOR TIME TO CORRECTING ACTION VS TIME TO EFFECT: N/A

- APPROVALS -

PRODUCT ASSURANCE ENGR: M. HOLTHAUS

DESIGN ENGR:

G.J. SCHWARTZ